

2008 DELAWARE COUNTY BRIDGE REPORT

Bridge Inventory and Inspection Summary

Road Name:	STOCKWELL RD.	Feature Intersected:	NO NAME SWALE
Route #:	T0050	Location:	0.2 MI. E. OF SR 61
Log Point:	0017	Township:	BERKSHIRE - KINGSTON
SFN:	2133903	Date Inspected (MMDDYY):	030509
Structure Type:	195	Deck Summary:	
Year Built:	1998	Superstructure Summary:	
Year Rehab:		Substructure Summary:	
Overall Length (ft):	11	Culvert Summary:	9
Roadway Width (ft):	26.0	Channel Summary:	6
Estimated ADT (year):	200 (04)	Approach Summary:	7
HS Operating Rating (tons):	45	GA and OS:	9A
HS Inventory Rating (tons):	36	<i>GA=general appraisal; OS=operational status</i>	
Posted Limit (tons):		<i>A=open to traffic; B=posting recommended; G=new bridge</i>	
% Legal Load:	150	<i>K=closed to all traffic; P=posted weight limit implemented</i>	
		Suff. Rating (SD or FO):	96.9 (C)
		<i>S = structurally deficient; F = functionally obsolete; * = culvert</i>	

Bridge Inspection Comments:

Item 53-no outlet for water leaving structure, 57-guardrail much too high at approaches;

Notes:

1. Item numbers in comments refer to BR86 bridge items.
2. Culverts are not scored for "deck, superstructure or substructure". Bridges are not for "culvert".
3. If posted weight limit is blank, the bridge can carry Ohio Legal Loads with no restriction.
4. GA=general appraisal or overall score from 1 to 9 (9 is excellent, 0=closed/failed)
5. HS Operating (OR) and Inventory ratings (IR) are total weight of truck (45 tons = HS25-44, 36 tons = HS20-44)
OR is maximum allowable load for occasional/permit loads. IR is limit for routine loads.